











COMPONENT CHECKLIST

M5X15  X4 A1	M6X15  X4 A2	M8X15  X4 A3	Ø16XØ6.2X1.5  X4 A4
--	--	--	---







X1

Open-wrench  X1 B1	5mm  X1 B2	6mm  X1 B3
--	--	---







X1




M8x12  X4 B4	Ø16XØ8.2X1.5  X4 B5	M8  X4 B6
--	---	---

X1

M8x70  X3 C1	Ø16XØ8.2X1.5  X12 C2	M8x60  X1 C3	Lag bolt  X4 C4	Lag bolt  X6 C5	Anchor  X6 C6
--	--	--	---	---	--

X1

 X1 AA	 X1 BB	 X2 CC	 X2 DD	 X2 EE	 X1 FF
--	---	---	--	---	---

 X1 GG	 X2 HH	 X1 JJ
---	---	---